









CITROEN

 Code	
<b>0-9</b>	
1580 SPI .....	12
220 A2.000 .....	12
8140.43N .....	22
8140.43S .....	22
9HT (DV6BTED4) .....	12
9HT (DV6BUTED4) .....	12
<b>D</b>	
D8B (XUD9TF) .....	14

 Code	
D8C (XUD9UTF) .....	14
D9B (XUD9A/U) .....	14
DHX (XUD9TF/BTF) .....	14
DV6B .....	12
<b>E</b>	
EW10J4 (RFN) .....	16
<b>F</b>	
F28TDCR .....	22

 Code	
<b>N</b>	
NFR (TU5JP4B) .....	12
<b>R</b>	
RFW (XU10J2U) .....	16
RHK (DW10UTED4) .....	18
RHV (DW10UTD) .....	18
RHX (DW10BTED) .....	20
RHZ (DW10ATED) .....	20

 Code	
<b>T</b>	
T8A (DJ5T) .....	22
T9A (DJ5) .....	22
THX (DJ5TED) .....	20
<b>W</b>	
WJZ (DW8) .....	16
<b>X</b>	
XU10J2 .....	20

CITROEN

 Code	
--	---

 Code	
--	---

 Code	
--	---

 Code	
--	---

CITROEN						
Ltr.						
1,6 DV6B 9HT (DV6BTED4) 9HT (DV6BUTED4)	55 kW (75 PS) BERLINGO HDI BERLINGO HDI 75	07/05→		<b>02-36567-01</b> ⑫ 	<b>61-36265-00</b> 0209.CA 76 Ø 1,25 mm 4 MLS <b>61-36265-10</b> 0209.CC 76 Ø 1,3 mm 5 MLS <b>61-36265-20</b> 0209.CE 76 Ø 1,35 mm 3 MLS <b>61-36265-30</b> 0209.CF 76 Ø 1,4 mm 6 MLS <b>61-36265-40</b> 0209.CG 76 Ø 1,45 mm 7 MLS 	<b>14-32206-01</b> 0204.A2 (10x) 
1,6 NFR (TU5JP4B)	66 kW (90 PS) BERLINGO	04/08→		<b>02-35055-01</b> ⑫ <b>08-35253-01</b> ⑬	<b>61-35055-00</b> 0209.1E 78,5 Ø MLS 	<b>14-32139-01</b> 0204.81 (10x) 
1,6 220 A2.000 1580 SPI	58 kW (79 PS) JUMPY	10/95→		<b>01-31755-03</b> ⑫ ⑬ <b>02-31755-06</b> ⑫ 0197.V3	<b>61-31755-00</b> 0209.P9 87,3 Ø 	

⑦ Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / junta para múltiple de admisión/de escape / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

<b>71-36567-00</b> 0249.C2 	<b>12-36587-01</b> 0956.51 (16x) <b>70-36587-00</b> 0956.51 16x	<b>40-76240-00</b> 0348.R5 4x 	<b>40-76919-00</b> 0348.R4 4x 	<b>71-35487-00</b> 0349.J8 	<b>70-31414-10</b> 
<b>81-35554-00</b> K ← 0127.42 40x55x6,4 A SL RD PTFE ACM <b>81-35553-00</b> K → 0127.43 85x105x8,8 A SL LD PTFE ACM <b>81-35552-00</b> N 0807.30 27x47x7 A SL RD PTFE ACM					
<b>71-35251-00</b> 2x 0249.A9 	<b>12-33512-02</b> 0956.40 (16x) <b>70-33512-00</b> 0956.40 16x	<b>11-35246-01</b> 0348.Q5 	<b>71-35067-00</b> 0349.J4 	<b>71-36469-00</b>	<b>71-35253-00</b> 0304.55 
<b>81-31863-00</b> K ← 0514.72 42x66x6 A SL RD FPM <b>81-23708-50</b> K → 0514.74 85x105x8 A SL LD FPM <b>81-34146-00</b> N 2x 0807.24 38x50x6 A SL RD FPM					
<b>71-31729-00</b> O 	<b>12-25837-01</b> 0956.22 (8x) <b>70-25837-00</b> 0956.22 8x	<b>71-35716-00</b> ⑦ 2x 	<b>71-31742-00</b> 0304.49 	<b>81-35883-00</b> N 30x52x7 AB SL RD FPM	

O oben / top / haut / arriba / superiore / сверху  
U unten / bottom / bas / debajo / inferiore / снизу



CITROEN						
Ltr.						
1,9 DHX (XUD9TF/BTF) D8B (XUD9TF) D8C (XUD9UTF)	66-68 kW (90-92 PS) JUMPER Bus TD JUMPER TD JUMPY TD	02/94→	 <b>02-25942-06</b> ⑫  <b>08-25918-02</b> ⑬	<b>61-33155-00</b> 0209.Q8 84 Ø 1,36 mm 1 MLS <b>61-33155-10</b> 0209.Q9 84 Ø 1,4 mm 2 MLS <b>61-33155-20</b> 0209.R0 84 Ø 1,44 mm 3 MLS <b>61-33155-30</b> 0209.R1 84 Ø 1,48 mm 4 MLS <b>61-33155-40</b> 0209.R2 84 Ø 1,53 mm 5 MLS <b>61-33155-50</b> 0209.T7 84 Ø 1,59 mm MLS <b>61-33155-60</b> 84 Ø 1,7 mm MLS 	<b>14-32177-01</b> 0204.73 (10x) 	
1,9 D9B (XUD9A/U)	51 kW (69 PS) JUMPER Bus D JUMPER D JUMPY D	02/94-04/02	 <b>02-25942-05</b> ⑫  <b>08-25918-02</b> ⑬	<b>61-29165-10</b> 0209.K0 84 Ø 1,6 mm 2 <b>61-29165-20</b> 0209.K1 84 Ø 1,7 mm 3 <b>61-31065-00</b> 0209.S5 84 Ø 1,4 mm 1 <b>61-31065-10</b> 0209.S6 84 Ø 1,45 mm 2 <b>61-31065-20</b> 0209.S7 84 Ø 1,5 mm 3 <b>61-31065-30</b> 0209.S8 84 Ø 1,55 mm 4 <b>61-31065-40</b> 0209.S9 84 Ø 1,6 mm 5	<b>14-32077-01</b> 0204.65 (10x) 	

⑦ Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / junta para múltiple de admisión/de escape / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>71-25942-00</b> 0249.91 	<b>12-25837-01</b> 0956.22 (8x) <b>70-25837-00</b> 0956.22 8x	<b>50-92244-00</b> ⚠ 1721.01  <b>71-33683-00</b> ⑦ 0348.J0 	<b>71-25918-30</b> 0304.34 	<b>81-25926-10 K ←</b> 0326.12 42x62x8 A RD FPM <b>81-34456-00 K →</b> 0127.28 90x110x7 A SL LD FPM <b>81-21798-30 N</b> 0236.14 35x50x8 A SL WD ACM	
<b>71-25942-00</b> 0249.91 	<b>12-25837-01</b> 0956.22 (8x) <b>70-25837-00</b> 0956.22 8x	<b>50-92244-00</b> ⚠ 1721.01  <b>71-33682-00</b> ⑦ 0348.89 	<b>71-25918-30</b> 0304.34 	<b>81-25926-10 K ←</b> 0326.12 42x62x8 A RD FPM <b>81-34456-00 K →</b> 0127.28 90x110x7 A SL LD FPM <b>81-21798-30 N</b> 0236.14 35x50x8 A SL WD ACM	



CITROEN						
Ltr.						
1,9 WJZ (DW8)	51 kW (69 PS) JUMPY D	04/98→	<b>01-34356-01</b> <sup>(12)</sup> <sup>(13)</sup> 0197.X6 +0127.28 +0326.22 +0807.14   <b>02-34356-01</b> <sup>(12)</sup> 0197.X5 +0807.14 	<b>61-33720-00</b> 0209.X0 84 Ø 1,26 mm 3 MLS <b>61-33720-10</b> 0209.X1 84 Ø 1,3 mm 4 MLS <b>61-33720-20</b> 0209.X2 84 Ø 1,34 mm 5 MLS <b>61-33720-30</b> 0209.X3 84 Ø 1,38 mm 6 MLS <b>61-33720-40</b> 0209.X4 84 Ø 1,42 mm 7 MLS <b>61-33720-50</b> 0209.1C 84 Ø 1,47 mm 4 MLS 	<b>14-32077-01</b> 0204.65 (10x) → 08469  <b>14-32116-01</b> 0204.97 (10x) → 08470→ 	
2,0 EW10J4 (RFN)	100-102 kW (136-138 PS) JUMPY JUMPY 16V	03/00→	<b>01-35045-01</b> <sup>(12)</sup> <sup>(13)</sup> <sup>(19)</sup> 0197.Y1 +0209.Z3 +0249.A4 +0249.A5 <b>02-35045-01</b> <sup>(12)</sup> <sup>(19)</sup> <b>08-37006-01</b> <sup>(13)</sup> 	<b>61-35045-00</b> 0209.Z3 85 Ø MLS 	<b>14-32234-01</b> 0204.A7 (10x) 	
2,0 RFW (XU10J2U)	80 kW (109 PS) JUMPER JUMPER Bus	02/94-04/02	<b>02-33650-02</b> <sup>(12)</sup> 0197.T4 +0209.J8 <b>08-25918-04</b> <sup>(13)</sup>	<b>61-33650-00</b> 0209.J8 87 Ø 1,35 mm 	<b>14-32077-01</b> 0204.65 (10x) 	

<sup>(12)</sup> Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

<sup>(19)</sup> mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con junta de culata MLS / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



<b>15-34356-01</b> 0249.95 +0249.97 <b>71-34353-00</b> U 0249.97  <b>71-34356-00</b> O 0249.95 	<b>12-25837-01</b> 0956.22 (8x) <b>70-25837-00</b> 0956.22 8x 	<b>71-34997-00</b> 0348.N1  <b>71-34998-00</b> 0348.N2  2x	<b>71-29465-00</b> 0349.H7  2x	<b>71-25918-30</b> <sup>(28)</sup> 0304.34 	<b>81-25926-10</b> K ← 0326.12 42x62x8 A RD FPM <b>81-34456-00</b> K → 0127.28 90x110x7 A SL LD FPM <b>81-25451-10</b> N 0514.15 35x50x7 A SL RD FPM
<b>71-34452-00</b> R 0249.A5  <b>71-34453-00</b> L 0249.A4 	<b>12-34439-01</b> 0956.45 (16x) <b>70-34439-00</b> 0956.45 16x 	<b>71-35903-00</b> 0348.P1  4x	<b>71-33853-00</b> 0349.H8 	<b>70-31414-10</b> 	<b>81-34454-00</b> K ← 0326.27 40x55x6,5 A SL RD FPM <b>81-34456-00</b> K → 0127.28 90x110x7 A SL LD FPM <b>81-34403-00</b> N 0236.44 36x50x7 A SL RD FPM 2x
<b>71-26237-00</b> 0249.48 	<b>12-25837-01</b> 0956.22 (8x) <b>70-25837-00</b> 0956.22 8x 	<b>71-33663-00</b> 0348.F6  2x <b>71-33738-00</b> <sup>(10)</sup> 0348.E6  2x	<b>71-26236-10</b> 0349.70  4x	<b>70-31414-10</b> 	<b>81-25926-10</b> K ← 0326.12 42x62x8 A RD FPM <b>81-34456-00</b> K ← 0127.28 90x110x7 A SL LD FPM <b>81-26244-10</b> N 0236.21 36x50x8 A RD ACM

<sup>(28)</sup> für Fahrzeuge ohne Klimaanlage / for vehicles without air conditioning / pour véhicules sans système de climatisation / para vehiculos sin aire acondicionado / per veicoli senza aria condizionata / оснащение / оборудование для автомобилей без кондиционера

O oben / top / haut / arriba / superiore / сверху  
 U unten / bottom / bas / debajo / inferiore / снизу



CITROEN												
Ltr.												
2,0 RHK (DW10UTD4)	88 kW (120 PS)	JUMPY HDI 120	01/07→		<b>61-34370-00</b> 0209.AV 86 Ø 1,25 mm    2 MLS <b>61-34370-10</b> 0209.AW 86 Ø 1,3 mm     3 MLS <b>61-34370-20</b> 0209.AX 86 Ø 1,35 mm    4 MLS <b>61-34370-30</b> 0209.AY 86 Ø 1,4 mm     5 MLS 	<b>14-35774-01</b> 0204.A6 (10x) 		<b>15-36571-01</b> 0348.S3 	<b>12-34399-02</b> 0956.48 (16x) <b>70-34399-00</b> 16x 0956.48	<b>71-36124-00</b> 0349.L9 	<b>70-31414-10</b> 	<b>81-36557-00</b> K ← 0127.47 42x62x7 A SL RD PTFE <b>81-36556-00</b> K → 0127.45 90x110x7 A SL LD PTFE <b>81-34144-00</b> N 0807.28 27x47x7 A SL RD FPM
2,0 RHV (DW10UTD)	62 kW (84 PS)	JUMPER Bus HDI JUMPER HDI	11/01→	<b>01-34398-01</b> <sup>(12)</sup> <sup>(13)</sup> 0197.X4 +0249.99   <b>02-34398-01</b> <sup>(12)</sup> 0197.X3 +0249.99  	<b>61-35815-00</b> 0209.X5 86 Ø 1,3 mm     1 MLS <b>61-35815-10</b> 0209.X6 86 Ø 1,35 mm    2 MLS <b>61-35815-20</b> 0209.X7 86 Ø 1,4 mm     3 MLS <b>61-35815-30</b> 0209.X8 86 Ø 1,45 mm    4 MLS <b>61-35815-40</b> 0209.X9 86 Ø 1,5 mm     5 MLS 	<b>14-35774-01</b> 0204.A6 (10x) 	<b>71-34398-00</b> 0249.99 	<b>12-34399-01</b> 0956.48 (8x) <b>70-34399-00</b> 8x 0956.48	<b>71-34401-00</b> 0348.N4 	<b>71-34402-00</b> 0349.H4 	<b>70-31414-10</b> 	<b>81-25926-10</b> K ← 0326.12 42x62x8 A RD FPM <b>81-34456-00</b> K → 0127.28 90x110x7 A SL LD FPM <b>81-34144-00</b> N 0807.28 27x47x7 A SL RD FPM



CITROEN						
Ltr.						
2,0 RHX (DW10BTED) RHZ (DW10ATED)	69-80 kW (94-109 PS)	JUMPY HDI	10/99→	<b>01-34398-01</b> ⑫ ⑬ 0197.X4 +0249.99   <b>02-34398-01</b> ⑫ 0197.X3 +0249.99 	<b>61-35815-00</b> 0209.X5 86 Ø 1,3 mm 1 □ MLS <b>61-35815-10</b> 0209.X6 86 Ø 1,35 mm 2 □ MLS <b>61-35815-20</b> 0209.X7 86 Ø 1,4 mm 3 □ MLS <b>61-35815-30</b> 0209.X8 86 Ø 1,45 mm 4 □ MLS <b>61-35815-40</b> 0209.X9 86 Ø 1,5 mm 5 □ MLS 	<b>14-35774-01</b> 0204.A6 (10x) 
2,0 XU10J2	81 kW (110 PS)	JUMPER JUMPER Bus	04/02→	<b>02-33650-02</b> ⑫ 0197.T4 +0209.J8 <b>08-25918-04</b> ⑬	<b>61-33650-00</b> 0209.J8 87 Ø 1,35 mm 	<b>14-32077-01</b> 0204.65 (10x) 
2,5 THX (DJ5TED)	79 kW (107 PS)	JUMPER Bus TDI JUMPER TDI	12/96-04/02	<b>01-34110-01</b> ⑫ ⑬ ⑰ 0197.W4 +0209.T5  <b>02-34110-01</b> ⑫ 0197.W3 +0209.T5 	<b>61-34110-00</b> 0209.T5 93 Ø 1,35 mm MLS 	<b>14-32156-01</b> 0204.87 (14x) +0204.88 (8x) 

⑫ Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑰ mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con junta de culata MLS / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



<b>71-34398-00</b> 0249.99 	<b>12-31306-07</b> 0956.38 (8x) → 08331 <b>12-34399-01</b> 0956.48 (8x) → 08332→ <b>70-31306-00</b> 0956.38 → 08331 <b>70-34399-00</b> 0956.48 → 08332→	<b>71-34401-00</b> 0348.N4 	<b>71-34402-00</b> 0349.H4 	<b>70-31414-10</b> 	<b>81-25926-10 K ←</b> 0326.12 42x62x8 A RD FPM <b>81-34456-00 K →</b> 0127.28 90x110x7 A SL LD FPM <b>81-34144-00 N</b> 0807.28 27x47x7 A SL RD FPM
<b>71-26237-00</b> 0249.48 	<b>12-25837-01</b> 0956.22 (8x) <b>70-25837-00</b> 0956.22	<b>71-33663-00</b> 2x 0348.F6  <b>71-33738-00</b> ⑩ 2x 0348.E6 	<b>71-26236-10</b> 4x 0349.70 	<b>71-25918-30</b> ⑳ 0304.34 	<b>81-25926-10 K ←</b> 0326.12 42x62x8 A RD FPM <b>81-34456-00 K →</b> 0127.28 90x110x7 A SL LD FPM <b>81-34403-00 N</b> 0236.44 36x50x7 A SL RD FPM
<b>71-33723-00</b> 0249.79 	<b>12-26058-02</b> 0956.19 (8x) <b>70-26058-00</b> 0956.19	<b>71-37096-00</b> 2x 0348.K4 	<b>71-37097-00</b> 0349.G4 	<b>70-31414-10</b> 	<b>81-34457-00 K ←</b> 0326.25 64x88x6 A SL RD ACM FPM <b>81-34458-00 K →</b> 0119.14 98x120x7 A SL LD ACM FPM <b>81-25451-10 N V</b> 0514.15 35x50x7 A SL RD FPM <b>81-17110-20 N H</b> 0807.26 32x52x7 A SL LD ACM FPM

⑳ für Fahrzeuge ohne Klimaanlage / for vehicles without air conditioning / pour véhicules sans système de climatisation / para vehiculos sin aire acondicionado / per veicoli senza aria condizionata / оснащение / оборудование для автомобилей без кондиционера

H hinten / rear / arrière / posterior / posteriore / сзади  
V vorne / front / avant / delante / anteriore / спереди



CITROEN						
Ltr.						
2,5 T8A (DJ5T) T9A (DJ5)	63-76 kW (86-103 PS) JUMPER Bus D JUMPER Bus TD JUMPER D JUMPER TD	03/94-04/02	<b>01-29160-01</b> ⑫ ⑬ 0197.T7 +0209.R3 <b>02-29160-01</b> ⑫ 0197.T6 +0209.R3	<b>61-29160-00</b> 0209.R3 93 Ø 1,6 mm 	<b>14-32164-01</b> 0204.74 (14x) +0204.75 (8x) 	
2,8 F28TDCR	94 kW (128 PS) JUMPER HDI	02/02-06/06		<b>61-33950-00</b> 0209.OC 1,3 mm <b>61-33950-10</b> 0209.OE 1,4 mm <b>61-33950-20</b> 0209.OF 1,5 mm 	<b>14-32096-01</b> 	
2,8 8140.43N	107 kW (146 PS) JUMPER HDI	05/04→	<b>01-33951-10</b> ⑫ ⑭ 0197.Y2  <b>02-33951-10</b> ⑫ 0197.Y3 	<b>61-33950-00</b> 0209.OC 1,3 mm <b>61-33950-10</b> 0209.OE 1,4 mm <b>61-33950-20</b> 0209.OF 1,5 mm 	<b>14-32096-01</b> 	
2,8 8140.43S	93-94 kW (126-128 PS) JUMPER JUMPER Bus HDI JUMPER HDI	09/00→	<b>01-33951-10</b> ⑫ ⑭ 0197.Y2  <b>02-33951-10</b> ⑫ 0197.Y3 	<b>61-33950-00</b> 0209.OC 1,3 mm <b>61-33950-10</b> 0209.OE 1,4 mm <b>61-33950-20</b> 0209.OF 1,5 mm 		

⑩ Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора  
 ⑭ ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / sin retén cigüeñal / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



<b>71-33723-00</b> 0249.79 	<b>12-26058-01</b> 0659.19 (12x) <b>70-26058-00</b> 0956.19	<b>71-33687-00</b> 0348.K1 <b>71-33786-00</b> ⑩ 0348.F9 	<b>71-33688-00</b> 0349.E7 	<b>70-31414-10</b> 	<b>81-34457-00</b> K ← 0326.25 64x88x6 A SL RD ACM FPM <b>81-34458-00</b> K → 0119.14 98x120x7 A SL LD ACM FPM <b>81-25451-10</b> N ← 0514.15 35x50x7 A SL RD FPM <b>81-34142-00</b> N → ⑳ 0807.21 47,5x62x7 A SL LD ACM FPM <b>81-34143-00</b> N → ㉘ 0807.15 40x62x7 A SL LD ACM FPM
<b>71-33956-00</b> 0249.C3 	<b>12-34914-05</b> <b>70-34914-00</b> 8x	<b>71-33621-00</b> 4x 	<b>71-33654-00</b> 4x 0349.H5 	<b>71-83048-00</b> 500327440 NBR 	<b>81-90042-00</b> K → ㉙ 0514.A8 FPM
<b>71-33951-10</b> 0249.A0 	<b>12-34914-05</b> <b>70-34914-00</b> 8x	<b>71-33621-00</b> 4x 	<b>71-33962-00</b> 4x 	<b>71-33944-10</b> Gummi 	
<b>71-33951-10</b> 0249.A0  <b>71-33956-00</b> X 0249.C3 	<b>12-34914-05</b> <b>70-34914-00</b> 8x	<b>71-33621-00</b> 4x 	<b>71-33654-00</b> 4x 0349.H5 	<b>71-33944-10</b> Gummi  <b>71-83048-00</b> X 500327440 NBR 	

㉙ für Fahrzeuge mit Klimaanlage / for vehicles with air conditioning / pour véhicules avec système de climatisation / para vehiculos con aire acondicionado / per veicoli con aria condizionata / оснащение / оборудование для автомобилей с кондиционером  
 ㉘ für Fahrzeuge ohne Klimaanlage / for vehicles without air conditioning / pour véhicules sans système de climatisation / para vehiculos sin aire acondicionado / per veicoli senza aria condizionata / оснащение / оборудование для автомобилей без кондиционера

