



**KIA**

**KIA**

 Code 

**0-9**

4G64 ..... 722

6G74 ..... 724

**B**

B1 ..... 710



B3 ..... 710-712

B5 ..... 712

B6 ..... 714

**D**

D4CB ..... 722

 Code 

D4EA ..... 718

D4EA-F ..... 718

D4HB ..... 720

**F**

FE (16V) ..... 718



**G**

G4CP ..... 718

G4ED ..... 714

G4EE ..... 710

G4FA ..... 712

 Code 

G4FC ..... 714-716

G4GC ..... 720

G4HE ..... 710

G4HG ..... 710

G4JP ..... 720



G4KE ..... 722

**J**

J2 ..... 724

**K**

KJ ..... 724

 Code 

KRV6 ..... 722

**O**

OK24N ..... 716

OK26Y ..... 716

**R**

R2 ..... 722


RF ..... 720

**T**

T8 ..... 716-718

 Code 

 Code 

 Code 

 Code 

KIA						
Ltr.						
1,0 G4HE	45-46 kW (61-63 PS) PICANTO	09/05→	<b>01-53895-01</b> ⑫ ⑬ 20910-02H00 +21421-21030 +21411-02500 +22224-02500 (12x)  <b>02-53895-01</b> ⑫	<b>61-53895-00</b> 22311-02760 MLS 		
1,1 B1 <b>[NEW]</b>	38 kW (52 PS) PRIDE	01/91→		<b>61-52420-00</b> 73 Ø 		
1,1 G4HG	48 kW (65 PS) PICANTO	04/04→	<b>01-53895-01</b> ⑫ ⑬ 20910-02H00 +21421-21030 +21411-02500 +22224-02500 (12x)  <b>02-53895-01</b> ⑫	<b>61-53895-00</b> 22311-02760 MLS 		
1,3 B3	44-53 kW (60-72 PS) PRIDE	01/90→	<b>01-52677-01</b> ⑫ ⑬ <b>02-52677-01</b> ⑫	<b>61-52677-00</b> 72,9 Ø 		
1,3 B3	55-60 kW (75-82 PS) RIO	08/00-02/05	<b>01-53380-01</b> ⑫ ⑬ OK30C 10 270 <b>02-53380-01</b> ⑫	<b>61-53380-00</b> OK30C 10 271A 76,5 Ø MLS 	<b>14-55077-01</b> OK30C 10 135A (10x) 	
1,4 G4EE <b>[NEW]</b>	71 kW (97 PS) PRIDE RIO	03/05→	<b>01-53965-02</b> ⑬ KSN61 10 270 +21421-22020 	<b>61-53965-00</b> 22311-26603 	<b>14-55096-01</b> 22321-26000 (10x) 	



<b>71-53601-00</b> 22441-02400 	<b>12-53929-01</b> 22224-02500 (12x) <b>70-53929-00</b> 22224-02500 12x	<b>71-53421-00</b> 28411-02500 	<b>71-53599-00</b> 28521-02700 	<b>70-31414-10</b> 	<b>81-53232-00 K ←</b> 21421-21030 30x46x7 A SL RD NBR <b>81-53424-00 K →</b> 21443-02500 60x75x8 A SL LD NBR <b>81-53246-00 N</b> 22144-38001 35x50x8 A SL RD NBR
<b>71-52416-00</b> 	<b>12-54023-01</b> <b>70-54023-00</b> 8x	<b>71-52673-00</b> 	<b>71-52674-00</b> 	<b>71-52417-00</b> 	<b>81-53228-00 K ←</b> KKY01 12 602 30x44x7 A SL RD NBR <b>81-53404-00 K →</b> OK201 11 312 83x100x9 A SL LD MVQ <b>81-53228-00 N</b> KKY01 12 602 30x44x7 A SL RD NBR
<b>71-53601-00</b> 22441-02400 	<b>12-52772-02</b> 22224-02500 (12x)	<b>71-53421-00</b> 28411-02500 	<b>71-53599-00</b> 28521-02700 	<b>70-31414-10</b> 	<b>81-53232-00 K ←</b> 21421-21030 30x46x7 A SL RD NBR <b>81-53424-00 K →</b> 21443-02500 60x75x8 A SL LD NBR <b>81-53246-00 N</b> 22144-38001 35x50x8 A SL RD NBR
<b>71-52686-00</b> 	<b>12-52829-01</b> OKL02 10 155 (16x)	<b>71-52764-00</b> 	<b>71-53053-00</b> 	<b>10-52691-01</b>  <b>70-31414-10</b> 	<b>81-53253-00 K ←</b> 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53404-00 K →</b> OK201 11 312 83x100x9 A SL LD MVQ <b>81-53228-00 N</b> KKY01 12 602 30x44x7 A SL RD NBR
<b>71-53472-00</b> OK30C 10 235A 	<b>12-53473-01</b> OK30C 10 155B (8x)	<b>71-53469-00</b> OK30C 13 111C 	<b>71-53471-00</b> 28521-2X600 	<b>10-53474-01</b> 21522-2X00 +21521-2X00  <b>70-31414-10</b> 	<b>81-53253-00 K ←</b> 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53404-00 K →</b> OK201 11 312 83x100x9 A SL LD MVQ
<b>15-53967-02</b> 22441-26020 (1x) +22442-23500 (2x) +22443-23001 (4x) 	<b>12-53678-01</b> 22224-23500 (16x) <b>70-53678-00</b> 22224-23500 16x	<b>71-53969-00</b> 28411-26011 	<b>71-53971-00</b> 28521-26600 	<b>70-31414-10</b> 	<b>81-53972-00 K ←</b> 21421-22020 35x48x8 A SL RD FPM <b>81-53306-00 K →</b> 21443-22000 72x96x9 A SL LD MVQ <b>81-53246-00 N</b> 22144-38001 35x50x8 A SL RD NBR



KIA						
Ltr.						
1,4 G4FA	10/10→	77 kW (105 PS)	CEE'D	<b>01-54020-01</b> ⑫ ⑬ 20910-2BB01  <b>02-54020-01</b> ⑫ 20920-2BB01	<b>61-54020-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 	
1,4 G4FA	12/06→	77-80 kW (105-109 PS)	CEE'D PRO CEE'D	<b>01-54010-01</b> ⑫ ⑬ KSR62-10270 ① →08/08  <b>01-54015-01</b> ⑫ ⑬ KSR62-10270A ① 08/08-09/08  <b>01-54020-01</b> ⑫ ⑬ 20910-2BB01 ① 09/08→  <b>02-54010-01</b> ⑫ ① →08/08 <b>02-54015-01</b> ⑫ ① 08/08-09/08 <b>02-54020-01</b> ⑫ 20920-2BB01 ① 09/08→ 	<b>61-54010-00</b> 22311-2B000 78,5 Ø 0,5 mm MLS ① →08/08  <b>61-54015-00</b> 22311-2B001 78,5 Ø 0,5 mm MLS ① 08/08-09/08  <b>61-54020-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS ① 09/08→ 	
1,5 B3	09/00-02/05	72 kW (98 PS)	RIO	<b>01-53390-01</b> ⑫ ⑬ OK30E 10 270 <b>02-53390-01</b> ⑫	<b>61-53390-00</b> OK30E 10 271A 76,5 Ø MLS 	
1,5 B5	02/96-10/97	59 kW (80 PS)	SEPHIA	<b>01-53890-01</b> ⑫ ⑬ OK20W 10 270B <b>02-53890-01</b> ⑫	<b>61-53890-00</b> OB61L 10 271A 	

AS Auslaßseite / exhaust side / côté échappement / lado de escape / lato scarico / сторона выпуска



<b>15-54064-01</b> 22441-2B002 	<b>12-54071-01</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>70-54071-00</b> AS 8x 22224-2B000 <b>70-54072-00</b> ES 8x 22224-2B010	<b>71-54066-00</b> 28411-2B000 	<b>71-54067-00</b> 28521-2B400 	<b>70-31414-10</b> 	<b>81-54068-00</b> K ← 21421-2B020 26x37,5x6 A SL RD FPM <b>81-54069-00</b> K → 21443-2B000 76x108x8 A SL LD FPM
<b>15-54064-01</b> 22441-2B002 	<b>12-54071-01</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>70-54071-00</b> AS 8x 22224-2B000 <b>70-54072-00</b> ES 8x 22224-2B010	<b>71-54066-00</b> 28411-2B000 	<b>71-54067-00</b> 28521-2B400 	<b>70-31414-10</b> 	<b>81-54068-00</b> K ← 21421-2B020 26x37,5x6 A SL RD FPM <b>81-54069-00</b> K → 21443-2B000 76x108x8 A SL LD FPM
<b>71-53488-00</b> OK30E 10 235 	<b>12-53489-01</b> OK30E 10 155 (16x)	<b>71-53487-00</b> OK30E 13 111C 	<b>71-53486-00</b> OK30E 13 460C 	<b>10-53492-01</b> MB6F4 10 428  <b>70-31414-10</b> 	<b>81-53404-00</b> K → OK201 11 312 83x100x9 A SL LD MVQ <b>81-53491-00</b> N ← 34x52x7 A SL RD MVQ
<b>71-53923-00</b> OK2A1 10 235A FPM 	<b>12-53924-01</b> MB630 10 155 (8x) <b>70-53924-00</b> 8x MB630 10 155	<b>71-53926-00</b> OK201 13 111 	<b>71-53927-00</b> OK201 13 460A 	<b>10-53403-01</b> 21521 2X000 +21522 2X000  <b>70-31414-10</b> 	<b>81-53253-00</b> K ← OB3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53404-00</b> K → OK201 11 312 83x100x9 A SL LD MVQ <b>81-53228-00</b> N KKY01 12 602 30x44x7 A SL RD NBR

ES Einlaßseite / intake side / côté admission / lado de admisión / lato aspirazione / сторона впуска



<b>KIA</b>						
Ltr.						
1,6 B6	59 kW (80 PS) SEPHIA	09/93-10/97	<b>01-53890-01</b> (12) (13) OK20W 10 270B <b>02-53890-01</b> (12)	<b>61-53890-00</b> 0B61L 10 271A 		
1,6 G4ED <b>[NEW]</b>	82 kW (112 PS) RIO	03/05→	<b>01-53965-03</b> (12) (13) KSR61 10 270 	<b>61-53965-00</b> 22311-26603 	<b>14-55096-01</b> 22321-26000 (10x) 	
1,6 G4FC	85-93 kW (115-126 PS) CEE'D PRO CEE'D	12/06→	<b>01-54010-01</b> (12) (13) KSR62-10270 1 → 08/08  <b>01-54015-01</b> (12) (13) KSR62-10270A 1 → 08/08-09/08  <b>01-54020-01</b> (12) (13) 20910-2BB01 1 → 09/08→  <b>02-54010-01</b> (12) 1 → 08/08 <b>02-54015-01</b> (12) 1 → 08/08-09/08 <b>02-54020-01</b> (12) 20920-2BB01 1 → 09/08→ 	<b>61-54010-00</b> 22311-2B000 78,5 Ø 0,5 mm MLS 1 → 08/08  <b>61-54015-00</b> 22311-2B001 78,5 Ø 0,5 mm MLS 1 → 08/08-09/08  <b>61-54020-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 1 → 09/08→ 		

AS Auslaßseite / exhaust side / côté échappement / lado de escape / lato scarico / сторона выпуска



<b>71-53923-00</b> OK2A1 10 235A FPM 	<b>12-53924-01</b> MB630 10 155 (8x) <b>70-53924-00</b> MB630 10 155 8x	<b>71-53926-00</b> OK201 13 111 	<b>71-53927-00</b> OK201 13 460A 	<b>10-53403-01</b> 21521 2X000 +21522 2X000  <b>70-31414-10</b> 	<b>81-53253-00 K ←</b> 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53404-00 K →</b> OK201 11 312 83x100x9 A SL LD MVQ <b>81-53228-00 N</b> KKY01 12 602 30x44x7 A SL RD NBR
<b>15-10104-01</b> 22441-26801 +22443-23001 (4x) +22442-23500 (2x) 	<b>12-53678-01</b> 22224-23500 (16x) <b>70-53678-00</b> 22224-23500 16x	<b>71-10101-00</b> 28411-26900 	<b>71-53971-00</b> 28521-26600 	<b>70-31414-10</b> 	<b>81-53972-00 K ←</b> 21421-22020 35x48x8 A SL RD FPM <b>81-53306-00 K →</b> 21443-22000 72x96x9 A SL LD MVQ <b>81-53246-00 N</b> 22144-3B001 35x50x8 A SL RD NBR
<b>15-54064-01</b> 22441-2B002 	<b>12-54071-01</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>70-54071-00 AS</b> 22224-2B000 <b>70-54072-00 ES</b> 22224-2B010 8x	<b>71-54066-00</b> 28411-2B000 	<b>71-54067-00</b> 28521-2B400 	<b>70-31414-10</b> 	<b>81-54068-00 K ←</b> 21421-2B020 26x37,5x6 A SL RD FPM <b>81-54069-00 K →</b> 21443-2B000 76x108x8 A SL LD FPM

ES Einlaßseite / intake side / côté admission / lado de admisión / lato aspirazione / сторона впуска



KIA						
Ltr.						
1,6 G4FC	90 kW (122 PS)	CERATO	05/06→	<b>01-54010-01</b> <sup>(12)</sup> <sup>(13)</sup> KSR62-10270 [1] →08/08  <b>01-54015-01</b> <sup>(12)</sup> <sup>(13)</sup> KSR62-10270A [1] 08/08-10/08  <b>01-54020-01</b> <sup>(12)</sup> <sup>(13)</sup> 20910-2BB01 [1] 11/08→  <b>02-54010-01</b> <sup>(12)</sup> [1] →08/08 <b>02-54015-01</b> <sup>(12)</sup> [1] 08/08-10/08 <b>02-54020-01</b> <sup>(12)</sup> 20920-2BB01 [1] 11/08→	<b>61-54010-00</b> 22311-2B000 78,5 Ø 0,5 mm MLS [1] →08/08  <b>61-54015-00</b> 22311-2B001 78,5 Ø 0,5 mm MLS [1] 08/08-10/08  <b>61-54020-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS [1] 11/08→ 	
1,6 G4FC	92-97 kW (125-132 PS)	CARENS CEE'D PRO CEE'D SOUL	02/09→	<b>01-54020-01</b> <sup>(12)</sup> <sup>(13)</sup> 20910-2BB01  <b>02-54020-01</b> <sup>(12)</sup> 20920-2BB01	<b>61-54020-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 	
1,8 OK24N OK26Y <b>[NEW]</b>	82 kW (112 PS)	SEPHIA	01/95-10/97	<b>01-53385-03</b> <sup>(12)</sup> <sup>(13)</sup> OK9A0 10 270B  <b>02-53385-01</b> <sup>(12)</sup>	<b>61-53385-00</b> OK247 10 271C 81,5 Ø MLS 	<b>14-55095-01</b> OK247 10 135 (10x) 
1,8 T8	81 kW (110 PS)	SHUMA	10/97-03/01	<b>01-53385-01</b> <sup>(12)</sup> <sup>(13)</sup> OK2BC 10 270 <b>02-53385-01</b> <sup>(12)</sup>	<b>61-53385-00</b> OK247 10 271C 81,5 Ø MLS 	<b>14-55095-01</b> OK247 10 135 (10x) 

A außen / outside / extérieur / exterior / esterno / снаружи  
 AS Auslaßseite / exhaust side / côté échappement / lado de escape / lato scarico / сторона выпуска



<b>15-54064-01</b> 22441-2B002 	<b>12-54071-01</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>70-54071-00</b> AS 8x 22224-2B000 <b>70-54072-00</b> ES 8x 22224-2B010	<b>71-54066-00</b> 28411-2B000 	<b>71-54067-00</b> 28521-2B400 	<b>70-31414-10</b> 	<b>81-54068-00 K ←</b> 21421-2B020 26x37,5x6 A SL RD FPM <b>81-54069-00 K →</b> 21443-2B000 76x108x8 A SL LD FPM
<b>15-54064-01</b> 22441-2B002 	<b>12-54071-01</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>70-54071-00</b> AS 8x 22224-2B000 <b>70-54072-00</b> ES 8x 22224-2B010	<b>71-54066-00</b> 28411-2B000 	<b>71-54067-00</b> 28521-2B400 	<b>70-31414-10</b> 	<b>81-54068-00 K ←</b> 21421-2B020 26x37,5x6 A SL RD FPM <b>81-54069-00 K →</b> 21443-2B000 76x108x8 A SL LD FPM
<b>71-53481-00</b> OK247 10 235B 	<b>12-54581-01</b> OKL01 10 155 (8x) +OKL02 10 155 (8x) <b>70-54281-00</b> ES 8x OKL01 10 155 <b>70-54282-00</b> AS 8x OKL02 10 155	<b>71-53478-10 A</b> OK247 13 135D  <b>71-53479-00 I</b> OK247 13 111A 	<b>71-53476-00</b> OK2A5 13 460 	<b>70-31414-10</b> 	<b>81-53253-00 K ←</b> 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53541-00 K →</b> OK247 11 312 88x104x8,5 A LD MVQ <b>81-53243-00 N</b> OK013 10 602 34x48x7 A SL RD NBR
<b>71-53481-00</b> OK247 10 235B 	<b>12-52806-02</b>	<b>71-53478-00 A</b> OK2A5 13 135  <b>71-53479-00 I</b> OK247 13 111A 	<b>71-53476-00</b> OK2A5 13 460 	<b>70-31414-10</b> 	<b>81-53253-00 K ←</b> 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53541-00 K →</b> OK247 11 312 88x104x8,5 A LD MVQ <b>81-53243-00 N ←</b> OK013 10 602 34x48x7 A SL RD NBR

ES Einlaßseite / intake side / côté admission / lado de admisión / lato aspirazione / сторона впуска  
 I innen / inside / intérieur / interior / interno / внутри



KIA

KIA						
Ltr.						
1,8 T8	81-85 kW (110-116 PS)	CARENS CLARUS	07/96→	<b>01-53385-02</b> (12) (13) OK2CA 10 270 <b>02-53385-02</b> (12)	<b>61-53385-00</b> OK247 10 271C 81,5 Ø MLS 	<b>14-55095-01</b> OK247 10 135 (10x) 
2,0 D4EA	83-110 kW (112-150 PS)	CARENS CRDi CERATO CRDi MAGENTIS CRDi SPORTAGE CRDi	07/02→	<b>01-53447-01</b> (12) (13)  <b>02-53447-01</b> (12) 	<b>61-53395-00</b> 84 Ø 1,1 mm MLS <b>61-53395-10</b> 84 Ø 1,2 mm 2 M MLS <b>61-53395-20</b> 84 Ø 1,3 mm 3 M MLS 	
2,0 D4EA-F <b>[NEW]</b>	103 kW (140 PS)	CEE'D CRDi CEE'D SW CRDi PRO CEE'D CRDi	09/07→	<b>01-53447-02</b> (12) (13) 20910-27G10  <b>01-53447-03</b> (12) (13)  <b>02-53447-02</b> (12) 20920-27G10 <b>02-53447-03</b> (12) 	<b>61-10010-00</b> X 22311-27401 84,5 Ø 1,1 mm MLS <b>61-10010-10</b> 22311-27411 84,5 Ø 1,2 mm 2 M MLS <b>61-10010-20</b> X 22311-27421 84,5 Ø 1,3 mm 3 M MLS 	<b>14-10372-01</b> 22321-27400 (10x) 
2,0 FE (16V)	94-98 kW (128-133 PS)	CLARUS RETONA SPORTAGE	04/94→	<b>01-53860-01</b> (12) (13) OK01C 10 270A  <b>02-53860-01</b> (12) 	<b>61-53860-00</b> OK013 10 271 	
2,0 G4CP <b>[NEW]</b>	102 kW (139 PS)	JOICE	02/00→	<b>01-54145-01</b> (12) (13) 20910-33F00  <b>02-54145-01</b> (12) 20920-33F00	<b>61-54145-00</b> 22311-33110 86,5 Ø 1,4 mm 	



<b>71-53481-00</b> OK247 10 235B 	<b>12-52806-02</b>	<b>71-53478-00</b> OK2A5 13 135 	<b>71-53476-00</b> OK2A5 13 460 	<b>70-31414-10</b> 	<b>81-53253-00</b> K ← 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>81-53404-00</b> K → OK201 11 312 83x100x9 A SL LD MVQ <b>81-53243-00</b> N ← OK013 10 602 34x48x7 A SL RD NBR
<b>15-53447-01</b> 22441-27400 +22443-27001 (4x) 	<b>12-53438-02</b> 22224-27900 (16x)	<b>71-53444-00</b> 	<b>71-53446-00</b> 	<b>70-31414-10</b> 	<b>81-53442-00</b> K ← 21335-27000 32x45x6 A SL RD NBR <b>81-53343-00</b> K → 21443-2A100 91x111x9 A SL LD MVQ <b>81-53441-00</b> N 22144-27000 36x50x8 A SL RD NBR
<b>15-53447-01</b> 22441-27400 +22443-27001 (4x) 	<b>12-53438-02</b> 22224-27900 (16x)	<b>71-10105-00</b> 28411-27400 	<b>71-10106-00</b> 28521-27400 	<b>70-31414-10</b> 	<b>81-53442-00</b> K ← 21335-27000 32x45x6 A SL RD NBR <b>81-53343-00</b> K → 21443-2A100 91x111x9 A SL LD MVQ <b>81-53441-00</b> N 22144-27000 36x50x8 A SL RD NBR
<b>71-52434-00</b> OK955 10 235 B 	<b>12-52829-01</b> OKL02 10 155 (16x)	<b>71-53054-00</b> OK9A4 13 111 	<b>71-53056-00</b> OFE3N 13 460 	<b>70-31414-10</b> 	<b>81-53243-00</b> K ← OK013 10 602 34x48x7 A SL RD MVQ <b>81-53342-00</b> K → 90x110x9 A SL LD NBR <b>81-53243-00</b> N ← 2x OK013 10 602 34x48x7 A SL RD NBR
<b>15-54219-01</b> 22441-33021 (1x) +22442-42001 (1x) +22443-33020 (4x) 	<b>12-52718-05</b> 22224-38000 (8x) +22224-38010 (8x)	<b>71-54221-00</b> 28411-33012 	<b>71-52908-00</b> 28521-33020 	<b>70-31414-10</b> 	<b>81-53279-10</b> K ← 21421-33114 44x60x7 A SL RD FPM <b>81-53981-00</b> K → 21443-33005 80x96x9 A SL LD FPM <b>81-53246-00</b> N 2x 22144-38001 35x50x8 A SL RD NBR





KIA						
Ltr.						
2,0 G4GC	102-105 kW (139-143 PS) CARENS CERATO SPORTAGE	04/04→	<b>01-53970-03</b> ⑫ ⑬ 20910-23A00A  <b>02-53970-03</b> ⑫	<b>61-53970-00</b> 22311-23700 		
2,0 G4GC	105 kW (143 PS) CEE'D PRO CEE'D	12/06→	<b>01-53970-02</b> ⑬ KSS61 10 270  <b>02-53970-02</b> ⑫	<b>61-53970-00</b> 22311-23700 		
2,0 G4JP	100 kW (136 PS) MAGENTIS	05/01→	<b>01-53410-01</b> ⑫ ⑬ 20910-38B01 <b>02-53410-01</b> ⑫	<b>61-53410-00</b> 22311-38100 86 Ø MLS 	<b>14-55075-01</b> 22320-38000 (10x) 	
2,0 RF	61 kW (83 PS) RETONA TD SPORTAGE TD	10/97→	<b>01-53115-01</b> ⑫ ⑬ <b>02-53115-01</b> ⑫	<b>61-53115-00</b> 0K054 10 271 87,6 Ø MLS 		
2,2 D4HB <b>[NEW]</b>	110-145 kW (150-197 PS) CARNIVAL CRDI SORENTO CRDI	11/09→	<b>01-10016-01</b> ⑫ ⑬ ⑳ 20910-2FB00  <b>01-10016-02</b> ⑫ ⑬ ⑳   <b>02-10016-01</b> ⑫ 20920-2FB00 <b>02-10016-02</b> ⑫  	<b>61-10016-00</b> ✗ 22311-2F110 86,5 Ø 1,2 mm MLS <b>61-10016-10</b> 22311-2F100 86,5 Ø 1,3 mm 1 M MLS <b>61-10016-20</b> ✗ 22311-2F120 86,5 Ø 1,4 mm 2 M MLS 	<b>14-10371-01</b> 22321-2F000 (10x) 	

⑳ ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>15-53976-01</b> 22441-23800 +22442-23500 (3x)  <b>71-53976-00</b> 22441-23800 	<b>12-53678-01</b> 22224-23500 (16x) <b>70-53678-00</b> 22224-23500 16x 	<b>71-53977-00</b> 28411-23600 	<b>71-53978-00</b> 28521-23005 	<b>70-31414-10</b> 	<b>81-53979-00</b> K ← 21421-23020 37,6x49x7,5 A SL RD FPM <b>81-53981-00</b> K → 21443-33005 80x96x9 A SL LD FPM <b>81-53246-00</b> N 22144-38001 35x50x8 A SL RD NBR
<b>15-53976-01</b> 22441-23800 +22442-23500 (3x)  <b>71-53976-00</b> 22441-23800 	<b>12-53678-01</b> 22224-23500 (16x) <b>70-53678-00</b> 22224-23500 16x 	<b>71-53977-00</b> 28411-23600 	<b>71-53978-00</b> 28521-23005 	<b>70-31414-10</b> 	<b>81-53979-00</b> K ← 21421-23020 37,6x49x7,5 A SL RD FPM <b>81-53981-00</b> K → 21443-33005 80x96x9 A SL LD FPM <b>81-53246-00</b> N 22144-38001 35x50x8 A SL RD NBR
<b>15-53484-01</b> 22441-38003 +22442-23500 +22443-38010 (4x) 	<b>12-52718-02</b> 22224-38010 (16x) <b>70-52718-00</b> 22224-38010 16x 	<b>71-53483-00</b> 28411-38000 	<b>71-52908-00</b> 28521-33020 	<b>70-31414-10</b> 	<b>81-53279-10</b> K ← 21421-33114 44x60x7 A SL RD FPM <b>81-53331-00</b> K → 21443-38010 85x103x8 A SL LD MVQ <b>81-53246-00</b> N 22144-38001 35x50x8 A SL RD NBR
<b>71-52291-00</b> 0K770 10 235B 	<b>12-52722-01</b>	<b>71-52438-00</b> 0K054 13 111 	<b>71-52439-00</b> 0K054 13 460B 	<b>71-52272-00</b> 	<b>81-53243-00</b> K ← 0K013 10 602 34x48x7 A SL RD MVQ <b>81-53342-00</b> K → 90x110x9 A SL LD NBR <b>81-53243-00</b> N ← 0K013 10 602 34x48x7 A SL RD NBR
<b>15-10001-01</b> 22441-2F000 +22443-2F000 +22133-2F000 (4x) 	<b>12-10130-01</b> 22224-2F001 (16x) <b>70-10130-00</b> 22224-2F001 16x 	<b>71-10127-00</b> 28312-2F000 	<b>71-10128-00</b> 28521-2F000 	<b>70-31414-10</b> 	<b>81-10409-00</b> K ← 21355-2F000 60x72x8 A SL RD FPM



<b>KIA</b>						
Ltr.						
2,2 R2	48 kW (65 PS) BESTA D	02/96→	<b>01-52440-03</b> ⑫ ⑬ <b>02-52440-03</b> ⑫	<b>61-52440-10</b> 87,5 Ø MLS 		
2,4 G4KE <b>[NEW]</b>	128 kW (174 PS) SORENTO	11/09→	<b>01-10012-01</b> ⑫ ⑬ 20910-2GJ01  <b>02-10012-01</b> ⑫ 20920-2GB01	<b>61-10012-00</b> 22311-25212 89,5 Ø MLS 	<b>14-10383-01</b> 22320-25000 (8x) +22321-25001 (2x) 	
2,4 4G64	102 kW (139 PS) SORENTO	08/02→	<b>01-53615-01</b> ⑫ ⑬ K0AH2 10 270 <b>02-53615-01</b> ⑫	<b>61-53615-00</b> 22311-38400 87,7 Ø 0,42 mm MLS 		
2,5 D4CB	103 kW (140 PS) SORENTO CRDi	08/02→	<b>01-53496-01</b> ⑫ ⑬ K0AH4 10 270A  <b>02-53496-01</b> ⑫ 	<b>61-53415-00</b> 22311-4A010 92,35 Ø 0,78 mm MLS <b>61-53415-10</b> 22311-4A000 92,35 Ø 0,84 mm MLS <b>61-53415-20</b> 22311-4A020 92,35 Ø 1 mm MLS 	<b>14-55072-01</b> 22321-4A000 (18x) 	
2,5 KRV6	110-121 kW (150-165 PS) CARNIVAL V6	08/99→	<b>01-35355-01</b> ⑫ ⑬ OK558 10 270B 	<b>61-35355-00</b> 2x 22311-3Y200 81 Ø MLS 	<b>14-55070-01</b> 2x OK9BV 10 135 (8X) 	

⑬ ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / sin retén cigüeñal / senza paraolio albero motore / без уплотнительного кольца коленчатого вала  
H hinten / rear / arrière / posterior / posteriore / сзади



<b>71-52291-00</b> OK770 10 235B 	<b>12-52722-01</b>	<b>71-52438-00</b> OK054 13 111 	<b>71-52439-00</b> OK054 13 460B 	<b>71-52272-00</b> 	<b>81-53243-00 K</b> ← OK013 10 602 34x48x7 A SL RD MVQ <b>81-53342-00 K</b> → 90x110x9 A SL LD NBR <b>81-53228-00 N</b> ← KKY01 12 602 30x44x7 A SL RD NBR
<b>71-10110-00</b> 22441-2G100 	<b>12-10122-01</b> 22224-2G000 (16x) <b>70-10122-00</b> 22224-2G000 16x	<b>71-10116-00</b> V 2x 28313-2G000  <b>71-10118-00</b> H 2x 28314-2G000 	<b>71-10111-00</b> 28521-25020 	<b>70-31414-10</b> 	<b>81-33489-00 K</b> ← 21421-25002 42x55x7 A SL RD ACM FPM <b>81-53331-00 K</b> → 21443-38010 85x103x8 A SL LD MVQ
<b>15-53484-01</b> 22441-38003 +22442-23500 +22443-38010 (4x) 	<b>12-52718-02</b> 22224-38010 (16x) <b>70-52718-00</b> 22224-38010 16x	<b>71-53483-00</b> 28411-38000 	<b>71-52908-00</b> 28521-33020 	<b>70-31414-10</b> 	<b>81-53279-10 K</b> ← 21421-33114 44x60x7 A SL RD FPM <b>81-53331-00 K</b> → 21443-38010 85x103x8 A SL LD MVQ <b>81-53246-00 N</b> 2x 22144-38001 35x50x8 A SL RD NBR
<b>71-53496-00</b> 22441-4A000 	<b>12-53499-01</b> 22224-4A000 (16x)	<b>71-53501-00</b> 28355-4A001 	<b>71-53502-00</b> 28513-4A001 	<b>70-31414-10</b> 	<b>81-53498-00 K</b> ← 48x62x8 A SL RD FPM <b>81-53497-00 K</b> → 21443-4A000 91x114x9 A SL LD FPM
<b>71-35404-00</b> L OK556 10 2F5  <b>71-53893-00</b> R OK9BV 10 2F5A 	<b>12-35406-01</b> OK9BV 12 123 (24x)	<b>71-35402-00</b> 2x OK9BV 13 111B 	<b>71-35403-00</b> 2x OK55W 13 460 	<b>70-31414-10</b> 	<b>81-22660-00 K</b> ← 32x45x7 A LD FPM <b>81-90049-00 K</b> → OK9BV 11 311 <b>81-34842-00 N</b> V 2x OK9BV 10 602A 30x40x7 A SL RD FPM <b>81-38342-00 N</b> H 4x OK9BV 10 604 30x40x7 A SL LD FPM

V vorne / front / avant / delante / anteriore / спереди





KIA						
Ltr.						
2,7 J2	03/97→	59-61 kW (80-83 PS)	BONGO D K2700 D PREGIO D	<b>01-53960-01</b> ⑫ ⑬ OK65A 10 270D <b>02-53960-01</b> ⑫	<b>61-53960-00</b> OK65A 10 271B MLS 	<b>14-55100-01</b> OVS01 10 137 A (7x) +OK413 10 136 A (11x) 
2,9 KJ	08/99-10/01	93 kW (126 PS)	CARNIVAL TD	<b>01-53370-01</b> ⑫ ⑬ K0AJ1 10 270  <b>02-53370-01</b> ⑫	<b>61-53370-00</b> OK56A 10 271B 100,5 Ø MLS 	
2,9 KJ	10/01→	106 kW (144 PS)	CARNIVAL CRDi	<b>01-53370-02</b> ⑫ ⑬ K0AJ1 10 270A  <b>02-53370-02</b> ⑫	<b>61-53370-00</b> OK56A 10 271B 100,5 Ø MLS 	
3,5 6G74	08/02→	143 kW (194 PS)	SORENTO V6	<b>01-53620-01</b> ⑫ ⑬ K0AH3 10 270 <b>02-53620-01</b> ⑫	<b>61-53620-00 R</b> 22311-39501 94 Ø 0,5 mm MLS  <b>61-53625-00 L</b> 22311-39502 94 Ø 0,5 mm MLS 	

⑫ Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



<b>71-53962-00</b> OK65A 10 236C ACM 	<b>12-53871-01</b> OK6A1 10 155 (8x) <b>70-53871-00</b> OK6A1 10 155 8x	<b>71-53963-00</b> 4x OK72C 13 111A 	<b>71-53964-00</b> OK65A 13 461B 	<b>70-31414-10</b> 	<b>81-53461-00 K ←</b> OVS01 10 602 53x70x11 A SL RD <b>81-53966-00 K →</b> 21443-4X000 90x110x9 A SL LD FPM
<b>71-53466-00</b> OK551 10 235 	<b>12-53494-01</b> OK551 10 155 (16x)	<b>71-53463-00</b> OK552 13 111 	<b>71-53464-00</b> OK551 13 461 	<b>70-31414-10</b> 	<b>81-53426-00 K ←</b> 50x68x9 A SL RD FPM <b>81-53342-00 K →</b> 90x110x9 A SL LD NBR <b>81-53467-00 N ←</b> OJE26 12 601A 38x52x7 A SL RD FPM
<b>71-53466-00</b> OK551 10 235 	<b>12-53494-01</b> OK551 10 155 (16x)	<b>71-53463-00</b> OK552 13 111 	<b>71-53493-00</b> OK551 13 461A 	<b>70-31414-10</b> 	<b>81-53426-00 K ←</b> 50x68x9 A SL RD FPM <b>81-53342-00 K →</b> 90x110x9 A SL LD NBR <b>81-53467-00 N ←</b> OJE26 12 601A 38x52x7 A SL RD FPM
<b>15-53687-01</b> 2x 	<b>12-52718-04</b> 22224-38000(12x) +22224-38010 (12x)	<b>71-53682-00</b> 2x 28411-39800  <b>71-53683-00</b> ⑩ 0 29215-39800  <b>71-53684-00</b> ⑩ U 29215-39850 	<b>71-53686-00</b> 2x 28521-39800 	<b>70-31414-10</b> 	<b>81-53254-00 K ←</b> 37x50x6 A SL RD MVQ <b>81-53343-00 K →</b> 21443-2A100 91x111x9 A SL LD MVQ <b>81-53453-00 N</b> 4x 22144-39001 30x42x8 SL RD MVQ

0 oben / top / haut / arriba / superiore / сверху  
U unten / bottom / bas / debajo / inferiore / снизу

